


1/2" SQ. DR.HEAVY DUTY AIR IMPACT WRENCH



8541-VG

INDEX NO.	DESCRIPTION	REQ'D NO.	INDEX NO.	DESCRIPTION	REQ'D NO.
★ 1	Housing Assembly (incl.2.3.10)	1	21	Gasket	1
● 2	Reverse Valve Bushing	1	22	Ball Bearing	1
● 3	Reverse Valve Bushing Gear	1	23	Rear End Plate	1
4	O-Ring	2	24	Rotor	1
5	Reverse Valve	1	25	Rotor Blade	6
6	Spring	1	26	Cylinder	1
7	Steel Ball	1	27	Rear End Plate	1
8	Reverse Valve Knob	1	28	Cylinder Dowel	1
9	Screw	1	29	Ball Bearing	1
● 10	Grease Fitting	1	30	Washer	1
★ 11	Throttle Valve Seat Assembly (incl.11-1.11-2)	1	31	Motor Clamp Washer	2
● 11-1	Throttle Valve Seat	1	32	Washer	1
● 11-2	O-Ring	1	33	Hammer Frame	1
★ 12	Throttle Valve Assembly (incl.12-1.12-2)	1	34	Hammer	2
● 12-1	Throttle Valve Pin	1	35	Hammer Pin	2
● 12-2	Throttle Valve	1	36	Standard Anvil	1
13	Spring	1	37	O-Ring	1
14	Exhaust Deflector	1	38	Socket Retainer	1
15	O-Ring	1	39	Gasket	1
16	Air Inlet	1	40	Hammer Case	1
17	Muffler Element	1	41	Bushing	1
● 18	Trigger Pin	1	42	Screw	3
★ 19	Trigger (incl.18)	1	TK	Tune-Up Kit { incl.4 (2) .6.7.13.15.17.21.25 (6) .37.38.39 }	
20	Retainer	1			

★ Must be Purchased in Assembly Set

● Recommended not to be purchased alone due to assembly difficulty

20181026R1