


1/2" SQ. DR.HEAVY DUTY AIR IMPACT WRENCH



1498-VG

INDEX NO.	DESCRIPTION	REQ'D NO.	INDEX NO.	DESCRIPTION	REQ'D NO.
★ 1	Motor Housing Assembly (incl.18.31)	1	25	O-Ring	1
2	O-Ring	2	★ 26	Cylinder Assembly { incl.46 (2) }	1
3	Reverse Valve	1	★ 27	Rotor Blade	6
4	Muffler Element	1	28	Rotor	1
5	Retainer	1	29	Front End Plate	1
6	Washer	1	30	Screw	3
7	Throttle Valve Seat	1	● 31	Spacer	1
8	Throttle Valve Assembly	1	32	Ball Bearing	1
9	Spring	1	33	Screw	4
10	O-Ring	1	34	Gasket	1
11	Washer	1	35	Hammer Pin	2
12	Air Inlet	1	36	Hammer Frame	1
13	Retainer	1	37	Hammer	2
14	Exhaust Deflector	1	38	Standard Anvil	1
15	Screw	1	39	O-Ring	1
★ 16	Trigger Assembly (incl.17)	1	40	Socket Retainer	1
● 17	O-Ring	1	41	Bushing	1
● 18	Bushing	1	★ 42	Hammer Case Assembly (incl.43)	1
19	O-Ring	1	● 43	Grease Fitting	1
20	Reverse Valve Knob	1	44	Reverse Knob	1
21	Spring	1	45	Reverse Knob	1
22	Pin	1	● 46	Steel Ball	2
23	Spring Pin	1			
24	Ball Bearing	1	TK	Tune-Up Kit { incl.2 (2).4.5.9.10.19.21.25.27 (6).34.39.40 }	

★ Must be Purchased in Assembly Set

● Recommended not to be purchased alone due to assembly difficulty

20200305R2